

52+94.3 = S.E. Cor. Sec. 14-89-14, lead plug in pavement

$$\begin{array}{r} 5294.3 \\ 2647.4 \\ \hline 2646.9 \end{array}$$

39+69.0 = $\frac{1}{4}$ $\frac{1}{4}$ fc. to S.

26+80.0 = E. Rof W. fc. to N+S. also W. Side of campus

26+47.4 = $\frac{1}{4}$ Set C.M.

25+96.0 = W. Rof W. fc. to N+S

19+95.0 = fc. to N.

13+25.5 = $\frac{1}{4}$ $\frac{1}{4}$ fc. to S.

11+49.0 = E. Side of farm yard

10+10.0 = farm house to S.

3+00.0 = farm hester Pech

0+0.0 = S.W. Cor. Sec. 14-89-14. Started at f'm to N+S.

N $\frac{1}{4}$ Cor. Sec. 23-T89N-R14W

S.E. Cor. Sec. 14-89-14

E.V.

S.E. Cor. Sec. 14-89-14
found reinforcing bar
running through
limestone badly

broken by frost
bar bent C.M. set
iron bar 1" 56 X 30"
limestone 14 X 5 X 12
tapered grade stake
1" 2 X 12

S.W. Cor. Sec. 14-89-14