

Sec. 74 E $\frac{1}{4}$ Cor.

Twp. Cedar Falls

Sec. 4 Twp. 89 Range 14

E $\frac{1}{4}$ Corner

FOUND:- Steel Reinforcing
Rod $\frac{1}{4}$ " x 24" long found
Rod $2\frac{1}{2}$ " underground.
Plumbed to center of Rod
and set Cement Monument
12" deep. Placed Rod on
North side of cement
Monument.

(over)

10-10-39

