


Found nothing on concrete slab as marking corner.

Est. Corner in midpoint of mile
 on right line SE 34 & E 1/4 SE 1/4
 lead plug in paving, & on double of
 1/4 distance.

Chip small cross in paving &
 tied in same as E 1/4 34-87-14.

E 1/4 COR. SEC. 34-87-14

45
 10-13-41
 Youngerman



lead plug at tie point

SE 34-87-14 found hwy ties