

570

0400 = S. E. car. sec. 5-89-11

13+22.7	1/4 1/4 f.c. E.
---------	-----------------

$$13 + 35.8 = 1/9 \frac{1}{9} \text{ ft. W.}$$

26+62.8 = E. 1/4 cor. sec. 5-89-11-Dug hole

12'x12'x4' found nothing but pieces of twisted wire 3' below original roadbed and about

1 S.E. of point established. Looked like it had been twisted around past at one time.

No old survey records on this at all. Farmer said there is no stone here. Established

cor. by splitting R.O.W. fc's and putting

on $\frac{1}{4}$ ft. West of $\frac{1}{4}$ ft. Very good. Return

1/9 tc's from ctr. sec 5 & ctr. sec 9. 1 Th

indicate point established.

$$39 + 98.7 = 3/9 \text{ f.c. W.}$$

51+65.0 = N. E. cor sec 5-89-11

E. - 1/4 Cor. sec. 5-89-11

10-25-38

Youngerman

