Sec. 7 NW Cor.

Twp. Cedar Falls

Sec. 7 Twp. 89 Range 14

N.W. Corner

Found:-Nothing Highway Commission has Reference Mon. out on ROW fences. No find rod or plug. Survey shows ℄ slab ≠ ℄ N≠S Rd to be corner HWY plat in 1920 also shows same. Chipped across in paving and tied same in as corner.

(over)


U.S.# 20
1 6
12 7