





The North 1/2 of the SE 1/4
of Section No 22 and the
SE of the SW were surveyed
for August Wright of
the SW of the SW of the
same Section were
surveyed for Jacob Harmon
and at request of each

Henry Gipe (Chairman for Wright) &
Wm Gipe appeared & sworn
Henry Gipe (Chairman for Harmon)
(Thomas Nelson) appeared & sworn

- A B Oak NW 1/4 E 39 L
- Cherry SW 1/4 E 42 L
- B B Oak SW 3/4 N 24 L
- B B Oak SW 3/4 E 27 L
- L Spruce NW 1/4 E 8 L
- B B Oak SW 3/4 N 14 L
- D Spruce SW 3/4 N 36 L
- D Spruce SW 3/4 E 36 L
- E B Oak NW 1/4 E 31 L
- B B Oak SW 1/4 N 9 L

Surveyed by Geo W Miller
Co Surveyor



Twenty acres on the North East
of the SE 1/4 of the SE 1/4 of Section
No 27 in Township 57 North of
Range 11 West

Surveyed February the 5th 1856
for William Gipe & at his
request August Wright
(Chairman for Wright) &
Wm Gipe appeared & sworn

- A Hickory SW 1/4 E 6 L
- B B Oak SW 3/4 N 24 L
- B B Oak NW 1/4 E 8 L
- B B Oak SW 3/4 N 14 L
- D Spruce SW 3/4 N 36 L
- D Spruce SW 3/4 E 36 L
- L Spruce NW 1/4 E 8 L

Surveyed by Geo W Miller
Co Surveyor