



SLSI 9-94
BHC0 03-09

INDEX OF ABBREVIATIONS

(M) = "Measured" Dimension	"NP" = Reflectorless EDM Meas.
(P) = "Platted" Dimension	"MLM" = Indirect Measure
(R) = "Record" Dimension	"CM" = Concrete Monument
(C) = "Calculated" Dimension	"SM" = Survey Marker Brand/Tag
"IGS" = Iowa Geodetic Survey	"PK" = PK/MAG Nail Spike Style
"WPA" = Works Progress Admin. Survey	
"Φ" = per George Miller Survey (BHCo Surveyor 1858-1860)	
"Σ" = per John Ball Survey (BHCo Surveyor 1866-1891)	
"N" = per Nathan Barber Survey (BHCo Surveyor 1908-1931)	