

**May 03, 2011**

**S.W. Cor. Sect. 26-T88-R14 (Update Info.)**

(LCcert Ref. file);

The crew (Claassen Eng.) found a PK Nail flush in the ACC overlay on 5/02/2011 at Wood St and Hudson Rd that fit FWK's reference ties [CES Bk 372-68] from 1993 and matches FWK's Recorded Plat Misc 305-274 dimensions also. The S.W. Cor. Sect. 26 is no longer an "X" in a RR spike. That has been overlayed with the ACC surface.

CES is not setting anything on this job.

We are only locating the Hudson High School Lot Lines for their 2011 Parking Lot Improvements.

Bill Adams (C.E.S.)

**December 5, 2012 (g.t. update)**

Yet, PLS Corner Cert. dated March 14, 2012 ref.'s MAG Nail as found in ACC, and Completed Corner Cert. filed per File 2012-00017008