


Resurvey of Hayden Rd.

Resurvey May 13th 1873.

the above
line from
state

Big
creek



1000
feet
from
road
to
creek

to
road
of
creek


Big
creek

the above
line from
state

Resurvey May 13th 1873.

the above
line from
state

Big
creek



1000
feet
from
road
to
creek

to
road
of
creek


Big
creek

the above
line from
state

Resurvey May 13th 1873.

the above
line from
state

Big
creek



1000
feet
from
road
to
creek

to
road
of
creek


Big
creek

the above
line from
state

Resurvey May 13th 1873.

the above
line from
state

Big
creek



1000
feet
from
road
to
creek

to
road
of
creek


Big
creek

the above
line from
state

Resurvey May 13th 1873.

the above
line from
state

Big
creek



1000
feet
from
road
to
creek

</

as per map

1/4 Sec line
S. 1/4 Sec. of South side of Sec 33 T 88 N 12 W
B. 1/4 Sec. 1760 links
B. 1/4 Sec. 1760 links
B. 1/4 Sec. 1760 links

Township line on 80° 35' 0"

East 1750 links
70 rods

I hereby Certify that

The above is a correct Plat & field note
point 70 rods East of the South 1/4 Section corner of Sec 33 T 88 N 12 W
1750 links East of 1/4 Section Cor of South side of Sec 33 T 88 N 12 W } Bear
Thence N 70° E 600 links to Township line Bearing true Br 020° N 38° W 61 links then
Crep Millers Creek 72 links wide bears S 80° E at 757 links Crep Stokes Road bears S 1

Board of Notaries

Returners of Haystack Bonds

State of Iowa } Office of Comptroller
Black Hawk County

Whereas a part of the Bond in Section Township in Davis County known as the "Haystack Bond" has been Reassigned - between a bond of \$2000 made East of the South West corner of the South East Quarter of Section 1st 34th 1st Range (33) in Township of Egypt Egypt (88) North of Range of 1st 34th 1st Range (12) West of the 3rd 1st 1st the face the South East corner of said Section. 33, Township & Range aforesaid.

And the State & State Notaries have been placed in the office of the County Clerk as required by law

Therefore Notice is hereby given that the matters of said Returners will ~~be~~ be heard before the Board of Supervisors of said County at their next Session on 18th 1873, and unless some cause be shown against its doing, the said State & State Notaries will be appointed and said Bond established in accordance herewith

as required by law,

Witness my hand & official seal
this 1st day of May 1873
J. W. Smith
Comptroller

To the Honorable board of
superiorso of Black Hawk County Iowa

Good afternoon would

respectfully ask that a redurvey on
the Hayden roads ^{in Cedar township} be authorized
between the following points commencing
70 rods East of the South West corner
South East quarter and running
East to South East corner Section
33 Township 88 Range 12

said ~~survey~~ original survey being
imperfect the board are ~~for~~ request
to the original report for the proof
of such defects

Respectfully
Waltero April 9th 1893

Waterloo Black Hawk County Iowa ^{May 11/873}
To ^{the} Hon. board of Supervisors of
Black Hawk County State of Iowa
Being appointed to Resurvey a part of the
Hayden Road in Cedar Township which part
lies between a point 70 rods East of the SW Corner of
of the ~~SW~~ South East quarter of Section 33 Township
88 North of Range 12 West & the SE Corner of Section 33 Township
88 North Range 12 West after being duly Qualified I fur-
nish here my self ^{with} the field notes of Saice & Space & did on
the 13th day of May 1873 with the assistance of Jeremiah Gay,
& George McClure & proceed I did make the said resur-
vey of the same but I could not find any old marks
or monuments with said field notes I surveyed it from
both points & found no evidence on either survey. I enclose
you will find ~~find~~ the Plat of the ^{Survey} according to the
original field notes. which does not fit any feasible
Route to locate a County Road & also does not connect
with ^{the} above named points therefore if there ever was any location
of Saice Space Saice Location is lost & as the Commission
requires me to run East from a point 70 rods East of the SW Corner
of the SE 1/4 of Section 33 T88 R12 W or nearly as a practical
Route can be found ~~found~~ & I found that on the Saice
East & West line that there was a small space very impractical

& by varying a short distance from a direct line & forming
 a practical route therefore I located the said
 space the location of which you will also find
 annexed a Plat & field notes of the same
 being a part of the Report { John Ball Commissioner
 & would recommend { County Surveyor of
 that the supervisor appear { Blackhawk County
 of the location of the same. Iowa -

Bill of Expenses
 Blackhawk County Dr to John Ball Com &
 County Surveyor for copying field notes making
 said survey of ^{a part of} Hayden Road & making out
 Plats of the same 2 1/2 days at \$4.00 per day
 \$10.00

Jeremiah Gay one day at \$1.25 1.25
 & George McClure one day at \$1.25 1.25
 { Claimmen } \$2.50

I hereby certify that the above is correct.
 John Ball County
 Surveyor of Black
 hawk County Iowa