

Sec. 30 N $\frac{1}{4}$ Cor.

Twp. Lincoln

9-14-38


Sec. 30 Twp. 87 Range 14

N $\frac{1}{4}$ Corner

Found lead plug
in pavement

(over)

Sec. 19-87-14



Sec. 30-87-14