

Sec. 5<sup>3</sup>E<sup>4</sup> Cor.

Twp. Barclay

10-25-38

Sec. 43 Twp. 89 Range 11

W $\frac{1}{4}$  Corner Dughole 12'x12'x4'

Found nothing but piece of twisted wire 3" below original road bed and about 1 SE of point established. Looked like it had been twisted around a post at one time. No old survey records on this at all. Farmer said there is no stone here. Established cor. by splitting R.O.W. f.e.s and putting on  $\frac{1}{4}$  f.e. - R.O.W. &  $\frac{1}{4}$  f.e. very good. Rerun  $\frac{1}{4}$  f.e.s from etc. Sec. 5. Both indicate point established.

