

Sec. 2 E $\frac{1}{4}$ Cor.

Twp. Cedar Falls

Sec. 2 Twp. 89 Range 14

E $\frac{1}{4}$ Corner Found nothing except a cottonwood stump as called for by Original Gov. survey, however this stump not that old. Est. cor. by prorating Gov. survey, setting S.C.M. on true line + 2617.72' N of SE 2 + 2358.2' S of NE 2 89-14 which are prorated distance. Also set Meander Cor. on true line on N. Bank Cedar River + 1065.0' N of NE 11 + 3911.1' S. of NE 2 89-14

(over)

See Book #1 page 30
T99 - R 14