

Sec. 31 N $\frac{1}{4}$ Cor.

Twp. Cedar Falls

Sec. 31 Twp. 89 Range 14

N $\frac{1}{4}$ Corner

Found 1" diam x 22" long

Reinforcing Rod found 3" deep.

Lowered all evidence in

place and set top of cement

Monument 12" deep

(over)

10-18-39

