

Twp. Cedar Falls

Sec. 33 Twp. 89 Range 14

S.E. Corner

Found sandstone

7x 5 1/2 x 2 1/2 @ 50

iron bar $\frac{1}{2} \times 32$

Set C.M. onto

12" underground

Nov. 1-38

steel/corpost

CX15pt. Tel. pole

x 15pk. 900 pole

✓ CX15pt
✓ Can post

0.25

19.2

(A) spr brace
post

NE Cor. sec. 5-88-14

177.54

Хиспк пов. пол.