


Sec. 35 S $\frac{1}{4}$ Cor.
Twp. Cedar Falls

1923

Sec. 35 Twp. 89 Range 14

S $\frac{1}{4}$ Corner

Found Iron Bar $12" \times 31"$ long & Granite stone $4' \times 12' \times 19"$
Lowered all evidence in
place and set top of Cement
Monument $12"$ deep. Iron Bar



10-12-38

4.5.58

Brace post

corner post

Brace post

N¹/₄ 3-88-14

186.3'

52.5'

45.9'

53.5'

35.0'

32.8'

38.0'

steel fence post

4.5.58
U.S. Hwy 58

