

Sta.

0+00

N $\frac{1}{4}$ cor. sec. 6-87-13, dug hole 15' x 9' x 50' found nothing, Established corner, 40.55' East, S $\frac{1}{4}$ 33-88-13, and on True line, S $\frac{1}{4}$ 31-88-13 to SE 31-88-13 and NE cor. 6-87-13, this according to Gov. dist.; Proration of Gov. dist. so. side 31 gives 2647.1' SE 31 to S $\frac{1}{4}$ 31, actually the dist. is 2640.8'; SW corner 31 was established by County, same is 6.3' too far West, I did not however, question the same or move it because it does fit the Roads N $\neq$ S, E $\neq$ W. S $\frac{1}{4}$ 31 $\neq$ N $\frac{1}{4}$ 36 as now set are 1.8' $\neq$ 1.5' South of right line btwn sec. corners.

Gov. closing dist. according to Sub-division would be 40.55'; No evidence Found by Random line of $\frac{1}{4}$ to from So.

N $\frac{1}{4}$ cor. sec. 6-87-13

Oct. 31-1990

Notes: Jacobson

Chain-Lien-

Chief. Youngerman.

