

NE 7-88-12

Found Nothing, Est. cor. by bearing & dist. from Cedar Stump given in Newton's Survey & John Ball's Survey which calls for a 14" Cedar South 50 links or 33.0'. found Cedar Stump o.k. No other bearing trees found.

S.E.M. 2" up.

Location Checks old surveys quite good by distances, but not as to line.

53+11.2 from SE 7-88-12
26+58.4 " E 1/4 7-88-12

seems to be some confusion in Newton's, & J. Ball's Survey Notes, & after studying same decided to set it as described above

N.E. cor sec. 7-88-12

Timber

53+11.2
3982.9
13283

30" Maple

14" Cedar Stump

Cedar

6-6-41

Youngerman

24" Box Elder

Corner Post

10" Ash

13283

13201 to Cor. post

E 1/4 7-88-12