

Sta.

53+54.9 = N.E. cor sec 11-T90-13-Found 3 1/2"

52+95.2 hole in pavement filled

48+96.8 with cement and (X) mark on

Top of cement (X) marks on

Expansion joint. Tied in

center of (X) mark.

45.0' S.E. of (X)-SPK POW pole.

53.5' N.E. of (X)-SPK Tel pole.

45.0' N.E. of Steel f.c post.

43.2' N.W. of (X)-SPK Tel pole.

44.5' N.W. of Steel cor post.

44.4' S.W. of (X)-SPK POW pole.

N.E. Cor. Sec. 11-90-13.

July 26, 1938

*Notes: Turnover

Chain: Bowser

