

Sta.

0+00

E $\frac{1}{4}$ cor. sec. 34-90-14

found I.P. (1"x24") on Sec. line.
ft. where farmer indicated same
set J.C.M. flush

this Iron pipe was set by Henry
Beisner, Cedar falls, midway b/w NE
& SE 34-90-14, & on line.

E $\frac{1}{4}$ cor. sec. 34-90-14

1-31-91

Youngerman

