

Sta. N $\frac{1}{4}$ cor sec 90-14

0+00

Dug & found iron bar Co. ties
 $\frac{1}{2} \times 24" \text{ I.P. } 1\frac{1}{2} \times 12"$ on sec. N & S which
 is the corner, checks old
 surveys by Ball, Newton,
 Schenck & Barber, within
 one foot, yet the corner by
 Rights should be 37.2' West of
 this spot. Believe an error
 in Original Gov. Survey which
 was not corrected is the cause
 of erroneous location. This is
 the corner all right, all right.
 Reran Old Sub-Div. survey Section 9, and

it checks very close, for Distance & line

33.5 S of MSPK cor fc post

39.0 S.E. of MSPK fc. post

117.0 N.E. of tel pole

33.1 N. of MSPK cor fc post

41.2 N.W. of MSPK gate post

60.3 N.W. of MSPK tel pole

35.5 S.W. of MSPK gate post

E. & C.R.I. & P.R.R. Tracks

N $\frac{1}{4}$ cor. sec. 9-90-14

9/3/70

Note

Youngerman
Chalm. Wiedert & Morelockold
Winslow station

2649.4'

25174.8'

Found
Iron Pipe & Bar

House

Bearing Trees

B.O. 141° N 81° W - 156.4'

Elm. N 73½° E - 57.4'

gone now