

K

EAST 1/4 COR. 17-90-12

FOUND TWISTED REBAR & CONC. MOUN.

MOUN. WACK OFF & BENT OVER. REBAR WAS AT
POINT WHERE MOUN. APPEARED TO HAVE BROKEN OFF