

$5348.8 = NE 21-88-12$, $52.55'$ N.R.L. Corner
 $52+29.8 = NE 21-88-12$, $34.75'$ N.R.L.
 89.0 Est. Cor. on true line & double
 of $\frac{1}{2}$ distance S.O.M. $3''$ up.
 found no bearing trace.
 Move $17.8'$ North $89.0'$ West

$38+88 =$ to angles North

$36+53.0$ Cor. post is $13.5'$ N.R.L.

$35+00 =$ to is $10.5'$ N.R.L.

$31+00 =$ to is $21.6'$ N.R.L.

$26+14.9 = N \frac{1}{4}$ Sec. 22-88-12 $25.45'$ N.R.L.

$23+00$ to is $27.5'$ N.R.L.

$15+56.7 =$ Cor. post $31.3'$ N.R.L.

$0+33.0 =$ WROW $N \frac{1}{2} S$.

$0+00 = NE 22-88-12$ $16.9'$ N.R.L.

$53+50.6$ computed dist
 $NE 20-00-12$ $NE 22$ $52.55'$ $\Delta 5$

