

Sec. 23 E $\frac{1}{2}$ Cor.

Twp. Spring Creek

Sec. 24 Twp. 87 Range 11

W $\frac{1}{4}$ Corner (See Over)



No Good

Niggerhead

W $\frac{1}{4}$ of SW $\frac{1}{4}$
Sec. 24.

Oak Hub

Oak Hub

38.55'

40.3'

34.6'

43.75'


Oak Hub

Oak Hub

W¹/₄ Cor. Sec. 24.

T 87 - R 11.

Dug and found nothing.
Obliterated Corner was established in the following way:
due to unexplained discrepancy in the original survey (corner can not be made to harmonize with the field notes in all directions), presumption was taken that the range line had been run straight and fixes East and West position of the Corner on the Section Line.
North and South position was fixed by the straight line through the center of Sec. 23.



Both fence N. & W. leading to the Corner are good. M.T.