

Sec 34 NE Cor.

Twp. Lincoln

9-6-38

Sec. 34 Twp. 87 Range 14

N.E. Corner

Found lead plug  
in E of pavement.

Lead plug center  
pavement

(over)

Sec. 27-87-14

Sec. 26-87-14

