

Sec. 34N $\frac{1}{4}$ Cor.

Twp. Cedar

Sec. 34 Twp. 88 Range 12

N $\frac{1}{4}$ Corner

N. $\frac{1}{4}$ - SEC. 34 - 88-12

R.R. EMBANKMENT TOO DEEP TO LOOK FOR ST. N.E.

EST. THIS CORNER ON INTERSECTION OF SEC. P.C.

LINE WEST AND $\frac{1}{4}$ P.C. LINE FROM NORTH.

S.C.M. IS JUST BELOW R.R. TIES AND ON W. EDGE
OF TIES.

(over)

