

Sec. 34 E $\frac{1}{4}$ Cor.
Twp. Black Hawk

Oct. 10, 1938

Sec. 35 Twp. 88 Range 14

W $\frac{1}{4}$ Corner

Found lead

plug in & of
parent.

(X) spk. brace post

(X) spk. gate post

$\frac{1}{4}$ ft.

(X) spk. cor. post

(X) spk. brace post

(X) spk. cor. post

$\frac{1}{4}$ ft.

(X) spk. pow. pole

(X) spk. brace post

Sec 34-88-14

Sec 35-88-14

