

Sec. 1 N $\frac{1}{4}$ Cor.
Twp. Poyner

(Corrected) March 21, 1938

1935

Sec. 1 Twp. 89 Range 12

N $\frac{1}{4}$ Corner



BM 7-201

Sec 36-90-12

Gatepost E. side To

Farmyard

1.B. BM 7-208

steel cor. fc. post.

103.6'

set Iron Bar

50.0'

Gate post

1.B.

fc cor post

1/4 corner Sec. 1-89-12

Sec 1-89-12

Found iron bar on fc. line, this corner
established by County Engineer Set c.m. on
E top 12" deep.