

Sec. 20 E $\frac{1}{2}$ Cor.

Twp. Cedar Falls

Oct. 12-1939

1933

Sec. 20 Twp. 89 Range 14

E $\frac{1}{2}$ Corner

FOUND:- Hiway Ref W.

marker 4"x4"x36" with

steel Rod in top, Plumbed

to center of steel Rod and "IB." 33.0' 33.0' IB."

Set Cement Monument 12"

deep. Placed marker on

North side of cement

Monument.

(over)

10-25-39

