

Sec. 31 NW Cor.

Twp. Cedar Falls


1931

Sec. 31 TWP. 89 Range 14

N.W. Corner

Found: riggerhead
3"x5"x12" and a
twisted Reinforcing
steel Rod $\frac{1}{2}$ " square x 31" long.
Lowered all evidence in
place and set top of cement
Monument 12" deep.

(over)



10-18-39.

