

Sec. 32 NE Cor.

Twp. Cedar Falls

1933

Sec. 32 Twp. 89 Range 14

N.E. Corner



E Prim. Rd.

No. 57

West

Lead plug in

40.0 Conc Pavement

CONC R.P.

CONC R.P.

Found Iron Bar
and (x) mark in post

(over)

10/18/39

