

Sec. 36 SE Cor.

Twp. Cedar Falls

1-12-1923

Sec. 36 TWP. 89 Range 14

S.E. Corner


Found badly broken

Limestone $16" \times 10" \times 5"$

Oak Hub $2" \times 2" \times 16"$

Iron pipe $1\frac{3}{4}" \times 21"$

Set C.M. 12" deep



(over)

6/8/38

Orchard

NW 1-88-14



208.5'

