

Sta

0+00 = SE cor. Sec. 18-88-11.

0+33 = N. R. o. W. $\frac{1}{2}$ c. Run. E & W.

No $\frac{1}{4}$ $\frac{1}{4}$ fc.

26+09.4

check this right now good

No $\frac{3}{4}$ $\frac{1}{4}$ fc.

52+54.4 = S. R. o. W. $\frac{1}{2}$ c. Run. E & W.

54+86.8 = N.E. cor. Sec. 18-88-11

E $\frac{1}{4}$ cor. Sec 18-88-11

7-10-39


50

Notes Jacobson

Chain-Cutforth-Turner

Sec 18-88-11

Sec 17-88-11



1 x spk cor. pos.

1 x spk br.

