Doc ID: 006912860001 Type: GEN Recorded: 11/23/2015 at 10:15:09 AM Fee Amt: \$7.00 Page 1 of 1 Black Hawk County Iowa SANDIE L. SMITH RECORDER

File 2016-00009568

WAYNE CLAASSEN ENGINEERING AND SURVEYING, INC. P.O. BOX 898 WATERLOO, IOWA 50704-0898

PHONE: (VOICE) 319-235-6294 (FAX) 319-235-0028

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE _____, Township ___ 88 North , Range Land Survey Monuments situated in Section ____ 13 West ____ , of the Fifth Principal Meridian, _____ Black Hawk County, Iowa. Previously recorded in _ _ in County Recorder's Office. (book, page, document number, etc.) Monument Description and Remarks The following note from field books found in the Black Hawk County Engineer's Office: "At point indicated by random line dug hole 3ft sq. and found limestone 10"x10"x2" and remnant of old oak hub lowered all evidence in place and set CM on top with cap marked 1/8 set top C.M. 12" deep." Acquisition Plat in Document No. 2012—12461, Chad Marsh #17340 signed 4—21—2011, found 1/2" rebar . Plat of Survey in Document No. 2013—07386, Patrick J. Shepard #12265 signed 10—9—12, found 5/8" rebar. Went to location of S 1/4 Corner and did not find 5/8" rebar or 1/2" rebar. Set 1/2"X24" steel rebar with red cap #16775 based upon above noted Plat of Survey and Acquisition Plat. 000.00 DENOTES RECORD DIMENSION PLAN - VIEW FROM PLAT OF SURVEY 2013-07386 DENOTES RECORD DIMENSION FROM ACQUISITION PLAT 2012-12461 000.00* (000.00)DENOTES FIELD DIMENSION 019 Reason for filing certificate: ☑ There is no certificate on file with the Recorder's Office. ☐ Accepts corner position which differs from the one shown in above document. ☐ The corner monument was replaced or modified. ☐ The reference ties in above document were incorrect or missing. MIDAMERICAN ENERGY SUBSTATION PARCEL "F" DOC. No. 2013-07386 .89. FOUND PIN & YELLOW CAP #17340 SE CORNER SEC. 09-T88N-R13W (FOUND PK NAIL) DOC. NO. 2015-08427 SHAULIS ROAD SW CORNER CONCRETE SEC. 09-T88N-R13W (SET 'X' CUT ON CONCRETE) S 1/4 CORNER (48.4)SEC. 09-T88N-R13W (SET 1/2" X 24" STEEL 2642.26'* **GRASS** 2650.68'* 2642.08 REBAR & RED CAP #16775) (2650.58')(2642.06')DRAINAGE DITCH FOUND 5/8" REBAR BENT FOUND PIN & YELLOW CAP #17340 List Corners to be Indexed I hereby certify that this land surveying document was prepared and the related survey work was performed by me or under my direct personal supervision and that I am a duly Section Corners Twp Range

Licensed Land Surveyor under the laws of the State of lowa. Signature: David L. Scheil, L.S.

Date: NOV. 19, 7015 Lic. No. 16775

Pages or Sheets Covered by this Seal: THIS SHEET ONLY.

My license renewal date is December 31, 2016

