PAUL H. HELLAND, 1107 TECHNOLOGY PARKWAY, CEDAR FALLS, IOWA 50613, (319)-266-0161

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

OF				
Land Survey Monuments situated in Section	4	, Township	89	. Range
of the Fifth Principal Meridian, B	LACK HAWK	County.	Iowa.	
Previously recorded in Book, Page	2	·	. 10 (u.	
(Show reason for preparing this certificate, the evidence and de and monumentation found or placed.)	tailed proced	lures used in esta	blishing the corr	ner positions
Monument Description and Remarks: SURVEY DONE IN E 1/4 CORNER - FOUND NAIL IN CONCRETE SLAB 0.09' EAS				***************************************
SE CORNER - FOUND NAIL IN LEAD PLUG 2.36' EAST OF				
PLAN - V	/TEW			
(Show a minimum of three reference ties to durable physical objectable recovery of the corner.)		t monuments and	physical conditi	ons that will
•				
L TIES ARE TO "X" NAILS IN WOOD POSTS ALL TI	ES ARE TO	"X" NAILS IN WO	OD POSTS	*
65.05'		'//	65.52'	X
70.20,			PAUL H HELLAN	ID S
E 1/4 CORNER	SE CC	DRNER V	650.	Secretary A
HEREBY CERTIFY THAT THIS PLAT, MAP, SURVEY OR REPORT WAS MADE		l let Corre	rs to be Indexed	- -
THE OR UNDER UT DIRECT PERSONAL SUPERVISION AND THAT I AN A JLY REGISTERED LAND SUPPRIOR UNDER THE LAWS OF THE STATE OF LOWA			e io de indexec	1
NOL H. HELLAND, P.E. & R.L.S. IOWA REGISTRATION NO. 6505	Corners		Twp	Range
REGISTRATION EXPIRES DECEMBER 31, 1997	E 1/4	4	89	12
HELLAND ENGINEERING & SURVEYING, LTD. 1107 TECHNOLOGY PARKWAY CEDAR FALLS, IOWA 50613 319-266-0161	SE	4	89	12

226

720