

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

No Corner Certificate on File. Survey completed in the SE 1/4 SE 1/4 of Sec. 21-T89N-R12W.

PLAN VIEW

NW CORNER OF SE 1/4 SE 1/4

1"o.d. Pinched Pipe
NE Corner of W 10 Acres

S89°06'E
330.4'

32.11'

23.00'

23.14'

Set orange plastic tag & metal shiner N Face 8"Ø Tree

Set orange plastic tag & metal shiner SW Face 30"Ø Tree

Set orange plastic tag & metal shiner E Face 5"Ø Tree

Remnants of fence

S89°17¼'E
1319.4'

S89°17¼'E
1319.4'

Center
1"o.d. Pinched Pipe
Per 299 Misc. 415

E 1/4 Corner
Aluminum Disk
in P.C.C. Pavement
Per 301 Misc. 56

N00°00½'E
1325.7'

N00°01'E
1326.8'

DUE SOUTH
1327.6'

S89°14¼'E
1319.2'

S89°15¼'E
1319.8'

NW CORNER OF SE 1/4 SE 1/4

N00°00½'E
1325.7'

N00°00½'E
1326.5'

S 1/4 Corner
"Mag" Nail in A.C.C. Pavement
Per 328 Misc. 295

SE Corner
Aluminum Disk
in P.C.C. Pavement
Per 301 Misc. 58

(Assumed Bearing)

N89°12¼'W
1319.6'

N89°12¼'W
1319.6'


DUE SOUTH
1327.6'

21



HELLAND ENGINEERING & SURVEYING, LTD.
1107 Technology Parkway
Cedar Falls, Iowa 50613-6951
(319)-266-0161

(00.00') - Recorded As File Name: 04-135c1.dwg



Jeffrey P. Helland 3/1/04
Jeffrey P. Helland
License Number 16264
My license renewal date is December 31, 2005.
All pages or sheets are covered by this seal except:

LIST CORNERS TO BE INDEXED			
CORNER	SECTION	TOWNSHIP	RANGE
NW CORNER	21	89N	12W
SE 1/4 SE 1/4			

Re