

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

OF


Land Survey Monuments situated in Section 33, Township 89 N, Range 13W, of the Fifth Principal Meridian, _____ County, Iowa.
 Previously recorded in N/A (book, page, document number, etc.) in County Recorder's Office.

Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.)

Monument Description and Remarks: FOUND ALUMINUM MONUMENT SET IN PAVING 0.20'
EAST OF SANITARY SEWER MANHOLE RING. THIS MONUMENT WAS SET BY
BRICE PETRIDES ASS. IN THE COURSE OF THE ANDERBROUGH AVENUE PAVING PROJECT.

PLAN - VIEW

(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)



I hereby certify that the survey work was completed and this certificate was prepared by me or under my direct personal supervision and that I am a duly registered land surveyor under the laws of the state of Iowa.

Signature: F. William King
 Name typed or printed: F. WILLIAM KING
 Date: 5-10-1991 Reg. No. 8033



Corners	List Corners to be Indexed	Section	Twp	Range
SE	33	89N	13W	

MISC. BK. 295 P. 956