Doc ID: 003929690001 Type: GEN Kind: CORNER Recorded: 10/08/2009 at 03:50:32 PM Fee Amt: \$9.00 Page 1 of 1 Instr# 200900010808 Black Hawk County Iowa JUDITH A MCCARTHY RECORDER Book 1080 Page 87677 - 87677 File 2010-00007420

<u>Jeffrey P. Helland, 1107 Technology Parkway,</u> Cedar Falls, Iowa 50613-6951, (319)-266-0161

(319)-266-0161

LAND

HELLAN 16264 _AND

AWO1

I hereby certify that this land surveying document was prepared and the related survey work was performed by me or under my direct personal supervision and that I am a duly licensed Land Surveyor under the laws of the State of lowa.

License Number 16264
My license renewal date is December 31, 2009.
All pages or sheets are covered by this seal except:

Illland

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE OF LAND SURVEY MONUMENTS SITUATED IN SECTION NO. 18 _, TOWNSHIP NO._ 90 NORTH, RANGE WEST OF THE FIFTH PRINCIPAL MERIDIAN, **BLACK HAWK** COUNTY, IOWA. PREVIOUSLY RECORDED IN N/A (SHOW REASON FOR PREPARING THIS CERTIFICATE, THE EVIDENCE AND DETAILED PROCEDURES USED IN ESTABLISHING THE CORNER POSITIONS AND MONUMENTATION FOUND OR PLACED.) MONUMENT DESCRIPTION AND REMARKS: NO USPLSCC ON FILE. SURVEY COMPLETED IN THE SW FRL 1/4 NW FRL 1/4 OF SEC. 18-T90N-R11W. N. 1/4 CORNER: AUDITOR'S SURVEY BOOK 1 PAGE 390 DATED 5/25/1869 CALLS FOR *[STONE IN OLD MOUND]*. W.P.A. NOTES DATED 12/29/1941 CALLS FOR *[CM 1.2 S. OF R.L.]*. PLAT OF SURVEY BOOK 344 PAGE 19 DATED 12/14/1996 CALLS FOR *[FOUND PIN IN ASPHALT]*. FOUND NO. 4 REBAR @ APPROXIMATE C.L. OF A.C.C. PAVEMENT, FLUSH. PLAN VIEW (SHOW A MINIMUM OF THREE REFERENCE TIES TO DURABLE PHYSICAL OBJECTS, RELEVANT MONUMENTS AND PHYSICAL CONDITIONS THAT WILL ENABLE RECOVERY OF THE CORNER.) 18 SET NO 4 REBAR SET NO. 4 REBAR (NOT TO SCALE) 46°46 (FIELD ENTRANCE) LEGEND 40,721. PER AUDITOR'S SURVEY BK 1 PG 390 DATED 5/25/1869 (0.0')¢ 118°191/2' 123°09' (0.0')£ PER W.P.A. NOTES DATED 12/29/1941 (39.24 CHAINS/2589.8')¢ S 89°48' E 2591.4' E. CEDAR-WAPSI ROAD (A.C.C. PAVEMENT) 45.63, N 1/4 CORNER NW CORNER (20:031/2 CHAINS/1 S 00°043/1 W 1 SEC. 18-T90N-R11W FOUND 1/2"Ø IRON BAR IN A.C.C. PAVEMENT PER 334 MISC. 930 71°45½' 67.00 ENTRANCE /1*322.* 1328. SET NO. 4 REBAR .65% 87.05 SET NO. 4 REBAR NE CORNER SE 1/4 NW FRL 1/4 SET NO. 4 REBAR w/OPC @ NW FACE CORNER POST (BEARINGS ARE ASSUMED) SHINER = 8D NAIL & 1 5/16"Ø METAL SHINER BRASS TAG = 13/16"Ø BRASS TAG OPC = PLASTIC CAP (0=ORANGE, R=RED, Y=YELLOW) (00') RECORDED AS FILE NAME: 09-241C2.DWG HELLAND ENGINEERING & SURVEYING, LTD. 1107 Technology Parkway Cedar Falls, Iowa 50613-6951

Rec.

RANGE

11W

11W

LIST CORNERS TO BE INDEXED

SECTION

18

TOWNSHIP

90N

90N

CORNER

N 1/4 CORNER

S 1/4 CORNER