



1930



N
↑



£ LOCAL ROAD

50.43

MON IS 3' DEEP.
IRON PIPE OVER MON
6" BELOW SURFACE.

3-6-57

£X

Found limestone 10"x6"x4"
bad/broken old car hub
17"x2"x2" Q.M. 5cft 12" deep.

Found limestone 10"x6"x4"
 badly broken old oak hub
 17"x2"x2" c.m. set 12" deep.

