

Sec. 33 E $\frac{1}{4}$ Cor.

Twp. Barclay

J-26-39

Sec. 34 Twp. 89 Range 11

W $\frac{1}{4}$ Corner

Found limestone

12" x 7" x 3" old

Oak Hub very

rotten 2" x 2" x 18"

Iron pipe $\frac{1}{2}$ " x 24 $\frac{1}{2}$ " long

Pipe was driven in
center of oak hub.

Lowered evidence and

set a.m. on top

12" deep.

(over)

$\frac{1}{4} f_{cx}$

(x) Spr. brace post

(K) $\exists p \in K, f_c, \text{posts} \rightarrow$

年尺

 $\frac{1}{4} f_{cx}$

(x) Spr. brace post