


Sec. 11 N $\frac{1}{4}$ Cor.

Twp. Cedar Falls

Sec. 11 Twp. 89 Range 14


N $\frac{1}{4}$ Corner

Found limestone pieces on E side of E face corner
Post # 26328 from NE cor 11-89-14 according to
Cedar Falls City Engineers records Best cluster
of limestone on E. side of cor post. Land Owner
said corner was at that point. Located all evidence
in place and set C.M. with cap marked.



Set C.M. 12" deep.

IN CITY



↓ U.S. HY# 58 STRAIGHT SOUTH
INTERSECTS U.S. 20
E & W.