

N $\frac{1}{4}$ Cor. Sec. 1-T90N-R11W

At location indicated by random line
dug hole 5 ft. square x 18" deep.

Found Angle Iron 3 $\frac{1}{2}$ " long, set
by Bremer County Engineer.

Plumbed & set CM with cap marked:

36
|
1

Set top of CM 12" deep.

520' S of x-spikes in cor. post

455' SW of x-spikes in Willow tree 36" dia.

60.0' SW of x-spikes in fo. post

30.8' NW of x-spikes in Thornapple 10" dia

2' E of x-spikes in cor. post

N $\frac{1}{4}$ Cor. Sec 1-90-11 9-18-39

Farm Buildings

BREMER.

* notes: Hubbard

Chain Hubbard-Skope

* Co.

(X) Spk. Cor. post.

(X) Spk. Willow (36")

(X) Spk. fo. post.

(X) Spk. Cor. post 0.2' W. & C.M.

520'

455'

60.0'

30.8'

2'

Grove

Farm Buildings

(X) Spk. Thornapple (10")